



Climate Control Service

Service need: Condensation in your vehicle's air conditioning system promotes fungus, mold and bacterial growth that is blown into the passenger compartment. Add to this nauseating smell the sound of an A/C compressor making a clacking sound due to a depletion of oil.

Solution:

- Clean out the air conditioning lines, evaporator and ventilator and then kill any bacteria mold or fungi. Then, deodorize the entire A/C system and the vehicle's interior. Finally, after a complete inspection for leaks and wear, our technicians will measure and replenish the oil in the compressor.

Result:

- The air inside your vehicle will be much cleaner and 4 to 5 degrees cooler, thanks to increased efficiency.



Odors, bacteria, mold, spores, fungi, road grime, nicotine oils and debris accumulate in your car's air conditioning evaporator.



BG Climate Control Service restores heating/cooling efficiency and freshens interior air.